





dairy dispenser. Milk inside container Significant mold growth observed on indicated it was used very recently was not moldy or curdled which protected.

Significant mold growth observed on cleaned and food is not protected. FS 4 - Equipment is not properly dairy dispenser.

(closenb)




FS 13 – Evidence of pests. Mouse dropping observed



FS 13 – Open drain pipe allows for pest infiltration



FS 13 – Evidence of pests. Mouse dropping observed




FS 13 – Evidence of pests. Mouse dropping observed



FS 13 – Large openings allows for pest infiltration



FS 13 – Large openings allows for pest infiltration






protected.
Cover for dairy dispensing container is missing. Mold is growing directly above open milk dispensing container.

FS 4 & FS 15 – Equipment is not properly cleaned and food is not protected.

Cover for dairy dispensing container is missing. Mold is growing directly above open milk dispensing container.



FS 13 – Evidence of pests. Mouse dropping observed



FS 4 & FS 15 – Equipment is not properly cleaned and food is not protected.

Cover for dairy dispensing container is missing. Mold is growing directly above open milk dispensing container.